

Advance Steel 2014 / SP1



This document describes the improvements in **Advance Steel 2014 Service Pack 1**.

BOM

- [12754] New token and updated list format for the “Point to point” list to show the connected member part marks individually.
- [12916] Exploded anchor materials are correctly shown on lists.
- [12996] A particular issue highlighting groups in a specific list template is corrected.
- [13262] A particular stability issue during model extracts creation is corrected.
- [13313] Corrected saw length for beams that have a shorten with an angle on both directions.

DETAILING

- A new default to set unique cut view titles per multi sheet drawings.
- A new option to detail several drawings to one PDF files.
- A new option for weld preparation dimensions in single part drawings.
- Improved folded plate line presentation on drawings.
- Improved presentation for beams objects that have new edge and corner features.
- [7164] A particular case where visible lines do not appear on general arrangement drawings is corrected.
- [7625] A particular case where a plate could not be detailed due to collisions is corrected.
- [7801] A particular case where hidden lines appeared as visible on assembly drawings is corrected.
- [9854] A particular case where bolts are incorrectly placed on a customer folded plate is corrected.
- [10525] A particular case where objects in collision could not be detailed is corrected.
- [11846] A particular case where a folded plate weld preparation is not detailed on general arrangement drawings is corrected.
- [12323] An incorrect clipping line for tube sections on general arrangement drawings is corrected.
- [12492] Angle dimension text remains after a drawing update.
- [12681] Missing lines in a cut view for a specific plate are corrected.
- [12803] Camera details can show the entire model.
- [12869] Improved drawing opening speed on Advance CAD.
- [12910] Labels with “Max distance for combining” is also used in processes.
- [12928] A specific case where an incorrect existing drawing was used when detailing from the Drawing Style Manager is corrected.
- [13029] Anchors detailed as symbol no longer hide the anchor holes.
- [13069] Smart dimensions on holes are kept after a drawing update due to geometry changes.

- [13102] A particular issue where the Document Manager does not open on a customer model is corrected.
- [13264] The hole symbol for rotated bolts follows the rotation in the view.
- [13301] Material and coating name mapping on drawings is done automatically from AstorAddIn.mdb and the AstorBase.mdb if not otherwise specified.

GAM

- It is now possible to copy an entire line in the table editor. Changes in cells or lines need to be confirmed by pressing enter.
- [12896] Incorrect language strings on the Polish installation have been corrected.
- [12991] A stability issue when accessing the Default application is corrected.
- [13092] User defined compound sections are transfer by the “Convert database” application.

GENERAL

- Service Pack installer shows build number.
- Updated UK XOX bolts diameter 6 and 8 mm.
- Flange middle object snaps are available for tapered beams.
- If opening a file from an older version, a warning message for the file conversion will appear.
- [10533] Message regarding the return of the license is displayed when the platform is closed.
- [12581] It is possible to change the tool palette theme picture in the XML file.
- [12584] Improved speed for copy and paste of details.
- [12921] Improved speed on Xref connection if the path to the Xref files is not valid anymore.

IMPORT/EXPORT

- Improved GTC exchange for tapered beams.
- [12935] Bolts created by joints are shown with their properties in DWF files.
- [13018] Import Revit proposes per default the *.gtcx file format.

JOINTS

- New extended moment end plate connection dedicated for tapered beam situations.
- [7670] Railing: The angle post connection places the angle leg on the right side of the post.
- [10074] Railing: Horizontal middle handrail interrupts when intersecting the posts if the sloped distances between the axes is different than the horizontal ones.
- [10917] Element contour connections can be used in custom connections.
- [10988] Apex joint can be created also on polybeams.
- [11421] Shear plate also works correctly for polybeams as secondary members.
- [11604] Embed plate – clip angle: Possibility to change the hole tolerance and corrected angle position on angles, channels and hollow sections.
- [11771] Manual bolts on custom connections are updated after model modifications.
- [11788] Parametric cope creates the weld points correctly also if the connection is used on curved and polybeams.
- [11794] Railing: Correct post cut for slopped supporting beams.
- [11931] Single side end plate works for angles as secondary members.
- [11955] Manual features from custom connections are kept in case beams are split afterwards.
- [12418] Single tube braces: Transfer from horizontal to vertical main members work correctly.
- [12574] Single tube braces: Corrected for orientation setting “Perpendicular” with “Total” layout.
- [12580] Bolts on gauge line: “Outer” option shows only the exterior bolts.
- [12730] Bracing macro uses automatically the library entries.
- [13022] Stiffener has changed default creation on channels so that the stiffener is immediately visible.
- [13023] A particular case where the library settings in the spiral stair have not been used, is corrected.
- [13032] Single tube braces can be created if secondary beams are sloped and skewed.
- [13039] Truss: Corrected alignment parameter when applying a library entry.
- [13042] Knee of frame with haunch: A particular case where there connection is created on the opposite column side is corrected.
- [13042] A particular case where the single side endplate is not correctly created on curved beams is solved.
- [13049] Double side end plate: A particular issue where the end plates are created rotated is corrected.
- [13123] Split splice and moment macro works again.
- [13138] A particular case where the single side end plate was not copied multiple times correctly is corrected.
- [13178] Shear plate: Countersunk bolts create the corresponding hole.

- [13238] Parametric cope works correct on mirrored channel sections.
- [13243] Stiffener at UCS is correctly created also when the insertion point is not on the beam system line.
- [13251] Stiffener is correctly created on mirrored channel sections.
- [13261] Clip angle skewed is correctly created on curved secondary members.

MODELING

- Project explorer allows turning off a selected group.
- Match properties work for tapered beams.
- Tapered beam has improved default weld preparation creation.
- Cut at UCS works for folded plates.
- Improved grid intersections snap points.
- [362] Compound beams are displayed with the same color in 2D wireframe and realistic presentation type.
- [5235] Improved identical part detection for copied folded plates.
- [10626] Improved result on plate contours for the split plate at line command.
- [12279] Beams have all required grip points in perpendicular view setting.
- [12327] Two Xrefs inserted in the WCS no longer create a collision in between them.
- [12427] Queries for folded plates also show the folded plate relations.
- [12867] User attributes can be saved in isolated footings.
- [12872] An issue with polybeams on handrails after exploding them is corrected.
- [12891] An issue with the unfolding of conical folded plates is corrected.
- [12909] A particular case where folded plate could not be created is solved.
- [12919] Xrefs with Advance Steel objects are visible in shade mode after opening.
- [12952] A stability problem when closing the bolt dialog box after changing the hole tolerance without confirmation is corrected.
- [12955] Removed warning message while changing copied model views.
- [12958] Corrected graphic representation on a customer model.
- [12993] Improved miter cut for parallel plates.
- [13038] A particular case where the cut plate at UCS did not extend the plate is corrected.
- [13109] Objects are visible during orbit after the objects are unmarked.
- [13144] An issue with the presentation of conical special parts is corrected.
- [13150] Correct audit reporting for negative shortenings on tapered beams.
- [13212] Objects can be again selected after using “Show all” from the project explorer.
- [13272] Multi edit option for bolts brings the correct bolt property dialog box up.
- [13322] It is possible to change the user attributes of a single object from compound profiles.

NC

- A new default to turn on and off the scribing functionality in NC.
- Scribing in NC works for plates.
- Scribing in NC works for attached parts.
- [12816] Saw cut information for T sections in NC is flipped.
- [12874] Plate contours from circular features appear with arcs instead of points in NC files.
- [12914] Cosmetic change on the warning message when creating NC files for tapered beams.
- [13027] A particular issue with incorrect contour points for a custom plate is corrected.
- [13232] Corrected AK block for tube NC contour with development shape.
- [13307] A specific case with an incorrect saw cut in NC for a beam with a contour feature is corrected.

Note: The number in brackets [xxx] is the GRAITEC Helpdesk reference.

Advance Steel, Advance Concrete, Autodesk, AutoCAD, DWF and Revit are registered trademarks or trademarks of Autodesk, Inc. and/or its subsidiaries and/or affiliates in the USA and/or other countries. Graitec and Graitec Advance are registered trademarks of the Graitec group. All other brand names, product names or trademarks belong to their respective holders. Autodesk, Inc. and its subsidiaries Graitec SA and Graitec GmbH, reserve the right to alter product and services offerings, and specifications and pricing at any time without notice, and are not responsible for typographical or graphical errors that may appear in this document. © 2013 Autodesk, Inc., Graitec SA, and Graitec GmbH. All rights reserved.