

## Advance Steel 2013 SP2 / HotFix2

---



This document describes the improvements in **HotFix 2** for **Advance Steel 2013 Service Pack 2**.

## **GENERAL**

- A particular case where the section selection in joints causes a warning message is corrected.
- [11250] Twisted folded plate creation follows again the justification default.
- [12220] A particular case where a polyline could not be erased after creating a polygonal contour is corrected.
- [12309] Conical folded plates are created also between identical rectangular.

---

*Note: The number in brackets [xxx] is the GRAITEC Helpdesk reference.*

---